DUPLICATE

CABLE:

LABORATORY NO.

Truesdail Laboratories, Inc.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

DOUGLAS AIRCRAFT COMPANY

Internal Mail Code 211-40 **CLIENT**

3855 Lakewood Boulevard

Long Beach, CA 90846

DATE

TUSTIN, CALIFORNIA 92680

AREA CODE 714 . 730-6239

AREA CODE 213 . 225-1564

December 6, 1988

November 16, 1988

TRUELABS

Storm drain inspection - Fourth quarter **SAMPLE**

P.O. #T & M-23465-C

INVESTIGATION As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on November 16, 1988 at the Douglas, Torrance facility and Long Beach facility (003). The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory and analyzed according to the American Public Health Associatin's "Standard Methods," 16 Edition. The results are as follows:

Sample I.D.	<u>Date</u>	Time	Flow-gpd	Temp ^o F	pH Units
Long Beach	11-16-88	2:00	73,180	68	9.2
(003) Torrance	11-16-88			70	6.8

Le	ong Beach 003	Torrance	
•	Milligrams/Liter		
ROD (405.1)	41	420	
BOD (405.1) Settleable solids (160.5)	~ <0.1 ^a	<0.1	
Matal anamanded Saling limit.	1 44		
Oil and grease (413.1)	<1		

Respectually submitted, TRUESDAIL LABORATORIES, INC

bervisor

Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.